

Atmospheric Specifications

Operating	
Temperature	10° to 40° celsius
Humidity	0-75% RH non condensing
Atmospheric Pressure	700 HPa to 1060 HPa
Storage	
Temperature	-40° to 70° celsius
Humidity	10-90% RH non condensing
Atmospheric Pressure	500 HPa to 1060 HPa

[safety](#)

From:

<http://www.asiimaging.com/docs/> - **Applied Scientific Instrumentation**

Permanent link:

http://www.asiimaging.com/docs/atmospheric_spec

Last update: **2017/03/02 23:52**

